

## CHIP RESETTER FOR CANON CLI-8 / PGI-5

The OEM Canon CLI8 and PGI5 cartridges have chips, which serve to monitor the ink levels and to provide an on-screen message of “empty” when the ink levels run out. Our **CHIP RESETTER** allows you to restore the ink level monitoring function, and thereby override the “empty” or “out of ink” messages after you have refilled and reset your cartridge. This resetter is designed and guaranteed to reset the ORIGINAL Canon chips, but may not work on compatible (generic brand) chips.

This **CHIP RESETTER** is versatile: It will automatically identify the cartridge model and detect whether the chip on the cartridge is in a good state or not, then reset the chip. Since it is operated by a small replaceable battery, the number of resets it can offer is unlimited.

**The following OEM (original brand Canon) cartridge chips can be reset:**

PGI-5BK, CLI-8BK, CLI-8C, CLI-8M, CLI-8Y, CLI-8PC, CLI-8PM

**Corresponding printer models:**

PIXMA IP3300/PIXMA IP3500/PIXMA IP4200/PIXMA IP4300/PIXMA IP4500/PIXMA IP5200/PIXMA IP5200R/PIXMA IP6600D/PIXMA IP6700D/PIXMA MP500/PIXMA MP510/PIXMA MP520/PIXMA MP530/PIXMA MP600/PIXMA MP610/PIXMA MP800/PIXMA MP800R/PIXMA MP810/PIXMA MP830/PIXMA MP950/PIXMA MP960/PIXMA MP970/PIXMA MX700/ PIXMA MX850/ IX4000/ IX5000/PIXMA Pro9000 and more

