


Resetting The Estimated Ink Level Indicator

Hewlett Packard 51641A (#10), C1823A/D (#23), C6578A/D (#78) Color



- 1) Remove refilled cartridge from printer.
- 2) Cover the top left four contacts (copper circuits on back of inkjet cartridge) with a piece of scotch tape.(see Photo) Do not mash or rub tape on contact. Gently apply pressure in order to get tape to stick.
- 3) Place taped cartridge back in printer & close printer lid. Wait 20-30 seconds.
- 4) Lift printer lid. Wait 30-45 seconds. You may receive an error message or printer lights may blink. This is okay.
- 5) Remove cartridge from printer.
- 6) *Remove tape from left four contacts. Place tape on right four contacts. (See Photo 2)
- 7) Place taped cartridge in printer & close printer lid. Wait 20-30 seconds.
- 8) Lift the printer lid. Wait 30-45 seconds. You may receive an error message or printer lights may blink. This is okay.
- 9) Remove cartridge from printer.
- 10.) *Remove the tape from right four contacts.
- 11.) Place the cartridge in printer. Ink level Indicator should read cartridge is full. You may have to repeat process if cartridge does not read full.

*Note: Make sure that there is no remaining tape adhesive on contacts. Carefully examine the contacts to make sure no residue of tape adhesive is apparent on copper contacts. Gently blot any remaining adhesive off contacts. It is important that you do not rub or wipe the copper.

AccuBrite, Inc. is not affiliated with the listed printer manufacturers or their subsidiaries. The use by AccuBrite, Inc. does not imply endorsement by or association with the brand name owners. The listed manufacturers, printers and cartridges are used only for the purpose of showing the compatibility of this AccuBrite, Inc. product. All other trademarks, brand names and logos referenced in or on this product are the property of their respective owners. This material is protected by the copyright laws of the United States and other countries. It is illegal to reproduce these instructions. It may not be reproduced, distributed, or altered in any fashion by any entity (either internal or external to AccuBrite), except in accordance with applicable agreements or contracts of licensing, without the express written consent of AccuBrite, Inc.

Copyright © AccuBrite, Inc. 2003-2008. All rights reserved